


SMITH P1 CAD ENGINEERING DRAWING

Assembly Drawing



Side View

